| Work Orde November 11, 20 | | | | | | | | | | | | | Page 1 |
|---|--------------------------|------------------------------------|---|----------------------|---------------|-----------------------|--------------|--------------|---------------|------------|---------------|------------------|----------------|
| Revision ID: | D2989-19 D Rib | | 10000 | Accept | | | | | S | Setup | Start Stop | | |
| Start Date: Required Date: Reference: | 11/11/2009 18/11/2009 | Start Qty: 4.00 Req'd Qty: 4.00 | \$2 1 1 1 1 1 1 1 1 1 | , | | Cust Item Customer | | | | | | | |
| Approvals: | Process Pla | ın: <u>fl</u> | Date: | Tooling: SPC (Y/N): | <u>;</u> _ | | Date: | | I | Run | Start Stop | | |
| Sequence ID/ Work Center ID | | Operation Description | , | Set Up/ Run Hour | ·s | Draw Number | Draw Rev. | Plan Code | Accept Qty | Rej Qty | | Reject Number | Insp. Stamp |
| Draw Nbr D2989 | Rev Rev | vision Nbr | | | | | | | | | | | • |
| 100 Large Fab | | Large Fab | | 0.00 | | | | | 0 | | | | |
| Large Fab | | | oer dwg D2989□2- Deburr ar | nd remove identifica | | SA 09-12 | D -03 | | | | | *. | |
| QC Quality Control | | QC5- Inspect part com Memo | pleteness to step on W/O | 0.00 2 | 2 | rolizlas | | | (xx) | | | · · | |
| 120 - Packaging Packaging | | Identify as per dwg & Memo | Stock Location: | 0.00 | Sh 09-1 | 40 12-03 | | | 9 | | | | |

Work Order ID 53655



Page 2

November 11, 2009 3:15:51 PM

Item ID:

D2989-19

D

Rib **Item Name:**

Start Date:

Revision ID:

11/11/2009

Start Qty: 4.00 **Required Date: 18/11/2009**

Req'd Qty: 4.00

Accept

Setup Start

Stop

Reference:

Approvals:

QC:

Process Plan:

Operation

Date: Date: **Tooling:**

SPC (Y/N):

Set Up/

Date: Date: Run

Qty

Start Stop



Sequence ID/ **Work Center ID**

130

Description QC21- Final Inspection - Work Order Release

Run Hours

0.00

Draw Number

Cust Item ID:

Customer:

Draw Rev.

Plan Code

Accept Qty

Reject Reject Number

Insp.

Stamp

Quality Control

Memo

0.00

Ce 9-12,07

Picklist Print

November 11, 2009 3:15:56 PM

Work Order ID: 53655

Parent Item:

Comments:

D2989-19RevD

Parent Item Name: Rib



Start Date: 11/11/2009

Required Date: 18/11/2009

Start Qty: 4.00

Required Qty: 4.00

| Component | Item ID/ | |
|-----------|----------|--|
| Item Name | | |

Replacement Mfg/ Item ID

Purch

Bin **Primary** Item Location Last Location

Route Seq ID Unit of Measure

Qty on Hand

Kemaining Qty **Óty To Pick** Issued

Date **Issued**

Status

Page 1

M304TS0.750W.065

Purchased

No

100

479.3370 10.9440

| I di diidodd |
|--------------|
| |

| 304 SQ Tube .75x.75x.065W | |
|---------------------------|--|

| Warehouse | Loc Oty | Loc Code | |
|-----------------|-----------|----------|--|
| Location | | | |
| Main Warehouse | | | |
| MAT | 473.6842 | | |
| 113082 | 473.6842 | | |
| Main Warehouse | | | |
| WA | 5.6527947 | | |
| 112398 | 5.6527947 | | |

B113245

D2989-043 BASKET LID ASSEMBLY (MESH SHOWN LOCALLY FOR CLARITY) D2989-041 BASKET LID ASSEMBLY (MESH SHOWN LOCALLY FOR CLARITY) SHOP CODY RETURN TO ENGINEERIN , UNCONTROLLED CORY SUBJECT TO AMENDMENT

QTY -041 QTY -043 ITÈM P/N DESCRIPTION ,1 D2989-041 BASKET LID ASSEMBLY D2989-043 BASKET LID ASSEMBLY 2 D2506 3 LABEL PLATE D2512-7 RIB 4 1 15 2 D2581 MOUNTING BRACKET 16 D2989-3 RIB ٦,7 D2989-4 RIB 18 2 D2989-5 RIB 19 D2989-13 RIB .10 2 D2989-17 RIB 11 2 D2989-19 RIB .12 D3182-1 HINGE 2 D3442-3 SHIM .13 RIB ASSY (INBOARD) .14 1 D3827-041 MESH, BASKET LID ,15 D3832-3 MESH, BASKET LID 16 D3832-5 MESH, LID END .17 D3833-3 MESH, LID END 18، 2 D3833-5 RIB ASSY (BASKET LID, LH) 19 D3836-041 RIB ASSY (BASKET LID, RH) D3836-042 20 RIB ASSY (BASKET LID, LH) 21 D3838-041 RIB ASSY (BASKET LID, RH) 22 D3838-042 23 D3852-041 RIB ASSEMBLY 24 D3852-042 RIB ASSEMBLY

2

C

REVISED -041/-043 PARTS LISTS AND ADDED "ITEM"
COLUMN TO PARTS LIST (ZN D3-1); D3836-041 REPLACES
D2898-94-15; D3836-042 REPLACES D2898-10-15; D3838-041
REPLACES D2989-11-7; D3838-042 REPLACES D2989-2/-7;
D3852-041 REPLACES D2989-11; D3852-042 REPLACES
D2889-2; REMOVED D2327-3 (NOW INSTALLED ON D3836
DWG), D2989-11/-2/-7-15
(NOW ON D3836 DWG) AND D2989-11/-12 (NOW ON D3852
DWG), REASON: TO SATISFY "LEAN MANUFACTURING" PROGRAM мв 08.09.24 FRAME MATERIAL WAS 0.060 WALL; MESH MATERIAL UPDATED; DRAWING TRANSFERED TO "B" FORMAT AND CURRENT DRAFTING STANDARD AJS 08.06.20 ĴВ ADD SHIM UNDER HINGES, UPDATE LID DIMENSIONS PH 05.06.07 łΑ **NEW ISSUE** DS 00.10.27 REV. DESCRIPTION BY DATE DESIGN DART AFROSPACE LTD

| 000.07 | | J DAKI AEKOSTACE | LID |
|------------|-----|--------------------------|--------------|
| DRAWN | 7 | HAWKESBURY, ONTARIO, CAN | |
| CHECKED | RSS | DRAWING NO. | REV. D |
| MFG. APPR. | | D2989 | SHEET 1 OF 5 |
| APPROVED | TAP | TITLE | SCALE |
| DE APPR. | -# | BASKET LID ASSEMBLY | NTS |
| | | | A41 - No. |

DATE 08.09.24

WITHOUT PATICE WORK ORDER NO. 53655 131109-11-12

8

5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX 6) IDENTIFICATION: N/A 7) WEIGHT: D2989-041 = 26.50 lbs; D2989-043 = 15.50 lbs 8) WELD PER DART QSI 004

NOTES:
1) MATERIAL: N/A
2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT AS INDICATED PER DART QSI 005 4.4
SPRAY PAINT INSIDE SURFACE BLACK PRIOR TO APPLYING ANTI-SKID

 \triangle







